HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Gloucester Woman's Club (Longbridge Ordinary)
Northeast corner of intersection of U.S. Rt. 17
and St. Rt. 14
Gloucester vicinity
Gloucester County
Virginia

HABS No. VA-512

Addendum to Longbridge Ordinary Gloucester County Virginia

Documentation: 11 sheets (1979, 1980, including site plan, plans, elevations, sections, details)
10 exterior photos (1934, 1981)

14 interior photos (1981)

Photo VA-512-1 was transmitted to the Library of Congress in 1934.

Jet Lowe, Photographer Spring 1981

VA-512-2 GENERAL VIEW LOOKING NORTHWEST

VA-512-3 SOUTH SIDE

VA-512-4 CORNER VIEW, SOUTH AND EAST SIDES

VA-512-5 EAST SIDE

VA-512-6 EAST AND NORTH SIDES

VA-512-7 NORTH SIDE

VA-512-8 NORTH AND WEST SIDES

VA-512-9 DETAIL VIEW UNDER PORCH, SOUTH SIDE

VA-512-10 ENTRY/STAIRHALL WITH DOOR OPEN, FIRST FLOOR, LOOKING EAST

VA-512-11 ENTRY/STAIRHALL WITH DOOR CLOSED, FIRST FLOOR, LOOKING EAST

VA-512-12 LOOKING FROM SECOND FLOOR STAIRHALL LOCATED AT SOUTHWEST CORNER OF HOUSE TO STAIRHALL AT NORTHWEST CORNER

(Continued to page two)

Gloucester Woman's Club Index to Photographs HABS No. VA-512 (page 2)

- VA-512-13 FIRST FLOOR MEETING ROOM, LOOKING EAST TO FIREPLACE AND TO DOORS LEADING TO PANTRY
- VA-512-14 FIRST FLOOR MEETING ROOM, LOOKING WEST TO DOORS TO ENTRY HALL
- VA-512-15 SOUTHEAST CORNER STAIRHALL, SECOND FLOOR, LOOKING EAST
- VA-512-16 MEETING ROOM ("TAP" ROOM), SECOND FLOOR, FIREPLACE AND DOOR TO LADIES LOUNGE CAN BE SEEN ON EAST WALL
- VA-512-17 MEETING ROOM, SECOND FLOOR, LOOKING TO SOUTHWEST CORNER
- VA-512-18 WINDOW DETAIL, SECOND FLOOR MEETING ROOM
- VA-512-19 LOOKING SOUTH IN LADIES LOUNGE, LOCATED OFF OF SECOND FLOOR MEETING ROOM
- VA-512-20 LOOKING DOWN STAIRWELL TO FIRST FLOOR FROM ATTIC LEVEL
- VA-512-21 STAIR DETAIL FROM ATTIC LEVEL
- VA-512-22 CHILDREN'S BEDROOM IN ATTIC, LOOKING EAST
- VA-512-23 CHILDREN'S BEDROOM IN ATTIC, LOOKING WEST
- VA-512-24 GENERAL VIEW LOOKING NORTH SHOWING SOUTH SIDE OF HOUSE